


Stormwater Assets
Requiring Structure
Recovery

Legend

- BMP
- Weir
- Riser
- Pipe/O
- Unverified Structure
- Manhole
- Revisit
- Revisit - Traffic
- Surveyed
- Inlet
- Revisit
- Revisit - Traffic
- Surveyed
- Streams
- OpenChannel
- Pipe
- Revisit
- Revisit - Traffic
- Surveyed
- City Boundary
- City Neighborhoods
- City Neighborhoods
- Prioritized for Ph 1a Detailed Study



STORMWATER ASSETS CONDITION ASSESSMENT

